

**Problem: Pool Deck Settled Around Coping Causing Trip Hazard**

To raise this pool deck, the homeowner first chose a local, multi-service company. Company representatives claimed they could raise the deck through  $\frac{5}{8}$  inch holes pumping in a product called poly foam.

The company attempted to raise the pool deck but were unsuccessful at raising any slabs. The failed attempt left unsightly holes closer to 3" inches in diameter. In addition, the poly foam material stuck to the concrete surface leaving permanent stains.

**Solution: Hire a mudjacking specialist to fix the job**

Unlike the prior contractor, Concrete Chiropractor specializes in concrete raising. Our technicians raised and stabilized the pool deck back to its original height, therefore removing the tripping hazard. Our process pumped a lab-tested, natural product into smaller holes than left behind by the prior contractor, gradually lifting the slab.

**End result: Satisfied client**

Although poly foam stain damage left from the previous contractor was non-reversible, the homeowner was extremely satisfied that Concrete Chiropractor was able to save his pool deck.

**Project Summary**

Concrete Chiropractor was able to save the project where others had failed. While competitors heavily market a variety of products and services, we only specialize in concrete repair. Our time-proven system and product is backed up with a solid warranty. Our reputation speaks for itself, demonstrated repeatedly by our satisfied clientele and their referrals.

